'11 JUN 21 A10:37



STATE PROCUREMENT OFFICE STATE OF HEMERGENCY PROCUREMENT REQUEST

1. TO: Chief Procurement Officer	
2.FROM: Transportation/Airports/Hawaii-H/Kona Interna	itional Airport
Department/Division/Agency	
Pursuant to §103D-307, HRS, and Subchapter 10, Chapter 3-122, HA 3. Date 6/2/2011	The state of the s
s. Nature of the Emergency	4. After the fact XES NO
On May 2, 2011, a severe electrical storm damaged the runway 17/25	surface and rendered associated airfield equipment out-
of-service. Equipment included: 1) ten (10) runway lights, 2) windso	
(ASOS) weather unit, 4) the Precision Approach Path Indicator (PAP	i) glide stope.
e. Vendor: WASA Electrical Services Inc.	7. Price:
Address: 73-4118 Hulikoa Drive Kailua-Kona, Hawaii 96740	\$8,773.77
Description of goods, services, or construction to be purchase	ed
Diagnostics, troubleshooting and repair services. Labor, materials and	
provided.	
 Reason for Vendor Selection Technicians possess Airport Operations Area (AOA) clearances/ide 	entification required by TSA and are cognizant of simort
and FAA safety regulations. (2) Contractor highly experienced in airfi	
working on another project.	· · · · · · · · · · · · · · · · · · ·
worming our minates brolans	
And	
10. Direct questions to: Chauncey Wong Yuen	Phone: (808) 327-9520 × 221
10. Direct questions to: Chauncey Wong Yuen	
10. Direct questions to: Chauncey Wong Yuen Up 11. I certify that the information provided above is to the	ne best of my knowledge, true and correct.
10. Direct questions to: Chauncey Wong Yuen	ne best of my knowledge, true and correct.
10. Direct questions to: Chauncey Wong Yuen III 11. I certify that the information provided above is to the	JUN 20 2011
10. Direct questions to: Chauncey Wong Yuen Up 11. I certify that the information provided above is to the	ne best of my knowledge, true and correct.
10. Direct questions to: Chauncey Wong Yuen III 11. I certify that the information provided above is to the	JUN 20 2011
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Head 12. Chief Procurement Officer's comments:	JUN 20 2011 Date
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Head 12. Chief Procurement Officer's comments: Approval is granted based on the department's determination that	Date the replacement of the runway lights, windsock
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Flead 12. Chief Procurement Officer's comments: Approval is granted based on the department's determination that lighting, automated service observations system weather unit and equipment was necessary due to potential safety concerns to the Kenney	the replacement of the runway lights, windsock precision approach path indicator glide slope
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Flead 12. Chief Procurement Officer's comments: Approval is granted based on the department's determination that lighting, automated service observations system weather unit and	the replacement of the runway lights, windsock precision approach path indicator glide slope
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Flead 12. Chief Procurement Officer's comments: Approval is granted based on the department's determination that lighting, automated service observations system weather unit and equipment was necessary due to potential safety concerns to the Kenney	the replacement of the runway lights, windsock precision approach path indicator glide slope
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Flead 12. Chief Procurement Officer's comments: Approval is granted based on the department's determination that lighting, automated service observations system weather unit and equipment was necessary due to potential safety concerns to the Kenney	the replacement of the runway lights, windsock precision approach path indicator glide slope
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Flead 12. Chief Procurement Officer's comments: Approval is granted based on the department's determination that lighting, automated service observations system weather unit and equipment was necessary due to potential safety concerns to the K award is required to be posted on the Awards Reporting System.	the replacement of the runway lights, windsock precision approach path indicator glide slope cona airport employees and passengers. This
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Flead 12. Chief Procurement Officer's comments: Approval is granted based on the department's determination that lighting, automated service observations system weather unit and equipment was necessary due to potential safety concerns to the K award is required to be posted on the Awards Reporting System.	the replacement of the runway lights, windsock precision approach path indicator glide slope cona airport employees and passengers. This
10. Direct questions to: Chauncey Wong Yuen 11. I certify that the information provided above is to the Department Flead 12. Chief Procurement Officer's comments: Approval is granted based on the department's determination that lighting, automated service observations system weather unit and equipment was necessary due to potential safety concerns to the K award is required to be posted on the Awards Reporting System.	the replacement of the runway lights, windsock precision approach path indicator glide slope cona airport employees and passengers. This